Search Tool 使用说明 Search Tool Operation Guide

文档版本:V1.0.2 发布日期:2015-01-20

目录

(contents)

1. IP 云台机芯模组升级指导	3
(The IP Module Upgrade Guide 3)
2. IP 云台 LOGO 型号升级指导	8
(The IP Module Logo &Model Upgrade Guide8)

IP 云台机芯模组升级指导

The IP Module Upgrade Guide

第一步:解压 search_tool.rar 文件到当前目录,如果要使用英文界面,需要删除 "batchcontrol_zh-CN.qm"语言包文件,否则软件界面为中文。双击打开"BatchControl.exe" 文件,如下图所示:

1 step: extract the search_tool.rar file to the current directory, you should delete "batchcontrol_zh-CN.qm", Otherwise the software interface is Chinese. double-click to open the file "BatchControl.exe", as shown below:

🎍 excel	2016/3/8 11:55	文件夹	
퉬 Media	2016/3/8 11:55	文件夹	
퉬 qrcode	2016/3/18 10:11	文件夹	
AnyanDeviceIDGenerater.dll	2015/2/4 17:30	应用程序扩展	50 KB
BatchControl.exe	2016/2/14 9:32	应用程序	791 KB
batchcontrol_zh-CN.qm	2016/1/5 13:41	QM 文件	9 KB
🔏 config.ini	2016/2/16 11:29	配置设置	1 KB
🛍 dancelist.ini	2015/12/24 15:02	配置设置	1 KB
📄 debug.log	2016/2/16 8:45	文本文档	1 KB
🗿 debugger.ini	2016/3/8 9:03	配置设置	1 KB

第二步:点击软件界面"search"按钮,相关设备会出现在左侧列表内,如下图所示: 2 step : Click the software interface "search" button, the related equipment will appear in the left list, as shown below:

Batch		ol Poleo Config						-	- • • ×
hoos 1	Index	Serials	IP	Chip	Main Version	MC Version	Model	OSD Lan	Search
	1	10A5CA56E5ABBBA40A	192.168.0.99	Am_S2Lm	V1.0.2 Build 201511111356	ZoomCam_V1.0.2_build201511101818		zh-c	Modify IP
	2	1086B156AA32B82D17	192.168.0.172	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		en-w	Upgrade
	3	103D1A563B22297ED5	192.168.1.100	Am_A5S	V1.0.2 Build 201509151043	MiniPtz_V1.0.2_build201509021448		zh-c	Set Time Aging
	4	106A185676CAC71366	10.10.10.199	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		en-w	Test Show
	5	1078E8568D2773487F	192.168.0.176	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Restore
	6	1078F7568D2B2C5CED	192.168.0.171	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Simple Restore Full Restore
	7	1086BA56AA345A724F	192.168.0.177	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Reset Admin
	8	1086C356AA36944AB6	192.168.0.174	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Serial:
	9	103AB3563370393D36	192.168.0.173	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Super Code:
	10	1062C5566EF0B58822	192.168.0.178	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		zh-c	Reset Admin
1				117					Port HTTP: KTSP:

第三步:此步骤非常关键,升级前要确保芯片类型和升级文件是否一致, S2L 系列的升级 文件以"IPNC_S2I"开头做标识,A5S 系列的升级文件以"IPNC_Amba"开头做标示,海思 130 万系列升级文件以"IPNC_Hi3518"开头做标识。软件界面"chip"类型界面会显示搜索 到的设备主控芯片类型,必须与将要升级的文件保持一致,否则会导致设备异常挂起。

3 step: this step is very important, before upgrading to ensure chip types and upgrade files are consistent, S2I series of upgrade files to "IPNC_S2I IPNC_S2I" at the beginning of the label. ASS series of upgrading of file to "IPNC_Amba AMBA" at the beginning it's marked, Hass 130 million Series upgrade file begins with a IPNC_Hi3518 IPNC_Hi3518 do identification. Software interface "chip" type interface will display the search to the device master chip type, must be consistent with the file to be upgraded, otherwise it will lead to the exception of equipment hanging.

💼 Batch	Contro	ol				14 1					
Devices thoos In	v ndex	rideo Config Serials	IP	Chip	Main Version	MC Version	Model	OSD Lan		Search	
	1	10A5CA56E5ABBBA40A	192.168.0.99	Am S2Lm	V1.0.2 Build 201511111356	ZoomCam_V1.0.2_build201511101818		zh-c		Modi fy	CP
	2	1086B156AA32B82D17	192,168,0	Am A5S	V1.0.2 Build 201511191322	 MiniPtz V1.0.2 build201509241507		en-w		Upgrad	•
	3	103D1A563B22297ED5	192.168.1.100	Antrabs	V1.0.2 Build 201509151043	MiniPtz V1.0.2 build201509021448		zh-c		Set Tim	e
	4	106A185676CAC71366	10.10.10.199	Am A5S	V1.0.2 Build 201509160901	MiniPtz V1.0.2 build201509241507		en-w		Aging	
	5	1078E8568D2773487F	192.168.0.176	Am A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Restore		
	6	1078F7568D2B2C5CED	192.168.0.171	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Simple Rest	ore	Full Restore
	7	1086BA56AA345A724F	192.168.0.177	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Reset Admir		
	8	1086C356AA36944AB6	192.168.0.17,4	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Serial:	10A5CA5	BESABBBA40A
	9	103AB3563370393D36	192.168.0.173	A55	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Super Code:	SP14581	97914
	10	1062C5566EF0B58822	192.168.0.178	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		zh-c	1	leset Ad	nin
									Port		
									HTTP: 80		
									RTSP: 554		
•								F			
Select A	11	Inverse Chip: Al	1 -		Sele	cted : 0 Total : 10					

第四步:选中需要升级的设备的复选框,如果批量升级,可以单击 "select all" 按钮即可, 再点击 "update" 按钮,即可进入软件升级界面,如下图所示:

4 step: select the need to upgrade the equipment check box, if the batch upgrade, you can click "all select" button, then click the "update" button, you can enter the software upgrade interface, as shown below:

💼 Bat	hCont	rol		-		-			
Devic		Video Config							
hoos	Index	Serials	IP	Chip	Main Version	MC Version	Model	OSD Lan	Search
	1	10A5CA56E5ABBBA40A	192.168.0.99	Am_S2Lm	V1.0.2 Build 201511111356	ZoomCam_V1.0.2_build201511101818		zh-c	Modify IP
	2	1086B156AA32B82D17	192.168.0.172	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		en-w	Upgrade
V	3	103D1A563B22297ED5	192.168.1.100	Am_A5S	V1.0.2 Build 201509151043	MiniPtz_V1.0.2_build201509021448		zh-c	Set Tine
	4	106A185676CAC71366	10.10.10.199	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		en-w	Test Show
	5	1078E8568D2773487F	192.168.0.176	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Restore
	6	1078F7568D2B2C5CED	192.168.0.171	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Simple Restore Full Restore
	7	1086BA56AA345A724F	192.168.0.177	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Reset Admin
	8	1086C356AA36944AB6	192.168.0.174	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Serial: 10A5CA56E5ABBBA40A
	9	103AB3563370393D36	192.168.0.173	Am A5S	V1.0.2 Build 201511191322	MiniPtz V1.0.2 build201509241507		zh-c	Check Code: SP1458197914
	10	1062C5566EF0B58822	192.168.0.178	Am A5S	V1.0.2 Build 201509160901	MiniPtz V1.0.2 build201509241507		zh-c	Super Lode: Reset Admin
f Gelect	All	Inverse Chip. [Al	1 •	117	Sel•	eted : 10 Total : 10		•	Fort MTF: 60 HTSP: 554
1		III K HTODCA56F54	BBBA40AXe						
		Curve: 1							

第五步: 在"Admin Password"填写网络设备的密码,点击"select"按钮,找到相应的升级文件所处的位置,注意,所有的升级文件都以"zip"文件为标示,不需要解压,直接升级压缩文件即可,再点击"update"即可,升级过程中会有进度条提示,如下图所示。备注:升级过程中,切勿断电或者断网,否则很容易造成设备死机。升级完成后,软件会提示 status和错误状态。

5 Step: in the "Admin Password" fill in the network device password, click on the "select "button, find corresponding upgrade file position, pay attention to, all updates are to "zip "file is marked, do not need to extract, direct upgrade files can be compressed, and click" update ", upgrade process will have a progress bar, as shown below. Note: in the process of upgrading, not power or off the network, it is very easy to cause the device to crash. After the upgrade is complete, the software prompts status and error status.

💼 Upgra	ade					? <mark>x</mark>
Index		IP	Status	Error	Progress	
1	192	2.168.0.99	Upgrading	0	11%	
Admin P	assword [.]	admin				
Model	:				Auto Choose	
Path:	F:/IPNC_S	212.0.1_build	201603031830.zip		Select	Upgrade

🕋 Upgra	de	_	_	? <mark>×</mark>
Index	IP	Status	Error	Progress
1	192.168.0.99	Completed	0	100%
Admin Ps	ssword: admin			
Model:				Auto Choose
Path:	F:/IPNC_S212.0.1_build20	1603031830.zip		Select Upgrade

第六步: 软件提示升级 OK 后,等待 5-10 分钟,网络设备会自动重启,可以关闭软件,再 重新点击"search"按钮进行 IP 搜索,出现相关设备信息后,表明网络设备重启完成,此时 即可进入 IE 操作和设置网络设备相关功能。 **6 Step:** the software prompts upgrade OK, wait for 5-10 minutes, the network device will automatically restart, the software can be shut down, again, dick on the "search" button to search IP and related equipment information, indicating that the network equipment restart to complete. Then you can enter the IE operation and related function of network equipment is arranged.

The IP Module Logo & Model Upgrade Guide

第一步:打开"Custom Tool.exe"软件,如下图所示:

Step 1: Open the "Custom Tool.exe "software, as shown in the following figure:

AnyanDeviceIDGenerater.dll	2015/2/4 17:30	应用程序扩展	50 KB
🕋 BatchControl.exe	2016/5/5 8:30	应用程序	916 KB
batchcontrol_zh-CN.qm	2016/1/5 13:41	QM 文件	9 KB
🗊 config.ini	2016/3/12 15:05	配置设置	1 KB
🕼 CustomTool.exe	2016/6/14 9:19	应用程序	168 KB
🗊 dancelist.ini	2015/12/24 15:02	配置设置	1 KB
🗑 debugger.ini	2016/2/22 13:55	配置设置	1 KB
🗟 hssdk_a.dll	2014/4/7 22:02	应用程序扩展	1,541 KB
🚳 hssdk_k.dll	2013/9/24 13:53	应用程序扩展	2,213 KB
🗟 HW_H265dec_Win32D.dll	2015/9/17 8:17	应用程序扩展	306 KB
hwconfig.txt	2014/11/15 11:02	文本文档	1 KB
🚳 icudt.dll	2013/4/15 17:33	应用程序扩展	8,858 KB
📄 log4cplus.prop	2015/1/10 17:30	PROP 文件	2 KB
🗟 log4cplusU_vc9.dll	2013/9/6 16:47	应用程序扩展	315 KB
Microsoft.VC90.CRT.manifest	2009/7/12 0:08	MANIFEST 文件	2 KB

第二步:将提前制作好的 IE 登录 logo 和 IE 界面 LOGO,必须保存为 PNG 格式, 否则软件无法识别 logo 图片,IE 登录界面 LOGO 的图像最大尺寸是 82*27, IE 主界 面的 LOGO 大小最大尺寸是 108*36。选择相应制作好的文件,填写需要修改的 产品型号,点击 "generate" 按钮,生成相应的升级包,升级包的路径在软件里 有提示,如下图所示:

2 step: Ready in advance of IE login logo and IE interface LOGO, must be saved as PNG format, otherwise the software can not recognize the logo picture.IE login screen LOGO the maximum size of the image is 82*27, IE the main interface of the LOGO size is 108*36.Select the appropriate production of file, fill in the need to modify the product model, click the "generate" button to generate the corresponding upgrade package, upgrade the package path in the software with tips, as shown below:

	CustomToo	1.48		
	Packaging T	001		
	MainLogo:	ong08/Desktop/search_tool/LoginLogo.png	Select	Max_Size:82*27
	SubLogo:	ngO8/Desktop/search_tool/IE SubLogo.png	Select	Max_Size:108*36
	Model:	TEST-TEST	Sample:XXXX-XX	хх
	-Display Me	Generate]
1	(10:04:58)	upgrade_path: C:\Users\lidingzhongO8\Des	ktop\search_tool	\upgrade.zip

第三步:将生成的 upgrade.zip 文件通过"BatchControl.exe"软件,进行升级,或者通过登录 IE 进行升级,强烈建议不要修改 upgrade.zip 名称,否则可能会导致升级异常:

3 step: the generated file upgrade.zip through "BatchControl.exe" software, upgrade, or log in through IE upgrade, strongly recommended that you do not change the name of the upgrade.zip that might otherwise lead to upgrade abnormal

(1) 打开 "BatchControl.exe" 软件,和升级产品主程序的方法一样,如下图所示:

open the "BatchControl.exe" software, and upgrade the product main program, as shown in the following figure:

vices	Video Config							1
e Inde	Serials	IP	Chip	Main Version	MC Version	Model	OSD Lan	Madi fre TP
	1060695669A086DF12	192.168.0.105	Am_S2Lm	V2.0.1 Build 2016061318235	ZoomCam_V1.0.2_build201605051517		zh-c	Upgrade
2	1078F7308D2B2C3CED	192.108.0.171	Am_A35	V1.0.2 Build 201003021902	Wimpt2_V1.0.2_Duid201001201417		211-0	Set Time 🕇
3	1062C5566EF0B58822	192.168.0.178	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		zh-c	Aging
4	103AB3563370393D36	192.168.0.173	Am_A5S	V1.0.2 Build 201603021902	MiniPtz_V1.0.2_build201601261417		zh-c	Test Show
5	1074E75681891DAFA4	192.168.0.99	Am_A5S	V1.0.2 Build 201511191322	ZoomCam_V1.0.2_build201511171756		zh-c	Restore admin password
6	1086C356AA36944AB6	192.168.0.174	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Simple Restore Full Restor
7	1086B156AA32B82D17	192.168.0.172	Am_A5S	V1.0.2 Build 201509160901	MiniPtz_V1.0.2_build201509241507		en-w	Reset Admin
8	1086BA56AA345A724F	192.168.0.177	Am_A5S	V1.0.2 Build 201511191322	MiniPtz_V1.0.2_build201509241507		zh-c	Check Code: SP1466230289
9	00022E573EAC8AC4C8	192.168.0.233	Hi3516D	V1.0.2 Build 20160620100315			zh-c	Super Code:
10	10D7D0571A5CEAAD15	192.168.0.115	Hi3518EV200	V1.0.2 Build 20160608110025E	McuF0Pt_V1.0.1_build20160312		zh-c	Reset Admin
								Port
								HTTP: 8070
								RTSP: 1024

(2): 通过 "select" 按钮选择对应生成的文件,点击 "Upgrade",软件会自动提示升级状态,确保 status 为 "complete", progress 进度为 100%,如下图所示:

Through the "select" button to select the corresponding generated files, click "Upgrade", the software will automatically prompt to upgrade the status, to ensure that the status is "complete", progress progress is 100%, as shown below:

💼 Upgra	de	NAME AND ADDRESS	-	Married Contents of	? ×
Index	IP	Status	Error	Progress	
1	192.168.0.105	Completed	0	100%	
Admin Pa	assword: admin]
Madal				Auto Choses	-
model.	L				~
Path:	C:/Users/lidingzhongO8/D	esktop/search_tool/u	ıpgrade.zip		Upgrade

第四步: IE 登录验证,如果不修改产品型号,登录 IE 前,必须要清空 IE 系统缓存: (1)进入工具->"Internet 选项",点击删除所有的历史记录,如下图所示: 4 step: IE login authentication, without modifying the product model, log ago of ie must clear ie cache system: (1) into tools - > Internet Options, click the delete all the records of history, as shown below:



Internet 选项	
常规 安全 隐私 内容 连接 程序 高级	
宮拠 安全 陰私 內容 谨接 程序 高級 主页 若要创建主页选项卡,请在各地址行键入地址 (3)。 http://hao.360.cn/?z1002 使用当前页(C) 使用默认值(P) 使用空白页(3) 浏览历史记录 砂 剛條他时文件、历史记录、Cookie、保存的密码和网页表单信息。 砂 剛條(D) 设置(2) 酸素单信息。 砂 剛條(0) 设置(2) 酸大 更改默认的搜索提供程序。 设置(2) 透页卡 更改网页在选项卡中显示的方式。 设置(1) 娇色(0) 语言(1) 字体(0) 辅助功能(2)	融除浏览的历史记录 × 保留收藏夫网站数据(R) 保留 Cookie 和 Internet 临时文件,可以使您收藏的网站能够保存偏好选项并提高显示速度。 ////////////////////////////////////
· · · · · · · · · · · · · · · · · · ·	动共享您访问的详细信息的数据。

重新登录 IE,输入用户名,密码,即可看到如下界面: Re login IE, enter the user name, password, you can see the following interface:

Login Logo IP Camera	English 🖃
	Please login
	User Name admin
	Password •••••
	Anonymous 💼
	Login



全 备注:如果要修改产品型号,修改完成后,必须完全恢复默认后才会显示 客户的定制型号。

Note: if you want to modify the product model, the completion of the modification, the default will be fully restored after the display of the customer's custom models.